

Vehicle Damage Inspection Report

Inspection Details

Date & Time:	June 1, 2026, 11:00 am
Location:	Gallup, NM
Vehicle:	2025 Toyota Tacoma
VIN:	XXXXXXXXXXXXXX
Odometer:	4,787
Owner:	XXXXXX XXXXXX
Inspector:	Dolores M. Bernal

Inspection Findings

Damage is concentrated on the driver-side front corner of the vehicle. The front bumper assembly has been detached from the vehicle and was observed resting on the ground in front of the truck at the time of inspection.

The driver-side front fender exhibits significant crushing, deformation, and tearing. The driver-side headlamp assembly is displaced and damaged, with surrounding mounting components visibly broken.

The front grille assembly is detached from its normal mounting position and was observed separated from the vehicle. Damage extends into the front fascia, bumper cover, and associated trim components.

The hood exhibits visible deformation and misalignment along the driver-side front edge. Internal components within the driver-side front corner were exposed due to the extent of the damage.

The driver-side wheel well liner is torn and displaced. Mud and debris were observed within the damaged wheel well area. The driver-side front tire and wheel were present at the time of inspection, with no obvious tire failure observed.

Additional Comments: When checking the odometer with the vehicle powered on, multiple warning messages and error indicators were displayed on the dashboard screen. These warnings may be related to the damage sustained during the collision and associated sensor detection systems. The dashboard display itself appeared functional.

Documentation Images

20260603_121813.jpg



20260603_121819.jpg



20260603_121841.jpg



20260603_121849.jpg



20260603_121905.jpg

