

Vehicle Inspection Report

Inspection Date/Time	May 30, 2026, 1:15 pm
Location	Gallup, NM
Vehicle	2019 Chevy Silverado 1500
VIN	XXXXXXXXXXXXXX
Odometer	182,471 miles
Owner	XXXXXX XXXXXX
Insurance Co.	XXXXXXXXXX
Inspector	Dolores M. Bernal

Damage Description

Damage is concentrated on the passenger side of the vehicle and is consistent with a side-impact (T-bone) collision. The primary impact area is centered at the B-pillar between the front and rear passenger-side doors.

The front passenger door exhibits severe crushing, creasing, and deformation extending across the lower and center portions of the door skin. The rear passenger door also exhibits significant deformation and inward intrusion at the leading edge adjacent to the B-pillar. The B-pillar shows substantial structural damage with visible crushing and displacement.

Damage extends into the lower rocker panel beneath both passenger-side doors. The rocker panel exhibits buckling, creasing, and deformation along the impact zone.

Additional damage is visible on the passenger-side rear bedside panel and wheel arch area, including dents, creasing, and surface scratches. White paint transfer and scrape marks are present throughout the damaged area.

The passenger-side doors remain operable; however, visible panel misalignment, reduced body gaps, and structural deformation are present. Damage appears extensive and may involve underlying structural components not visible during the inspection.

No obvious tire damage was observed in the photographed areas. Vehicle was stationary during inspection and no determination regarding drivability or mechanical condition was made.

| Driver Notes

The driver stated that opening the passenger-side door in the impact area has become difficult following the collision. According to the driver, increased effort is required to open the door due to the damage sustained during the incident.

| Inspection Photographs



Reference: 20260528_134658.jpg



Reference: 20260528_134628.jpg



Reference: 20260528_134534.jpg



Reference: 20260528_134432.jpg



Reference: 20260528_134412.jpg



Reference: 20260528_134356.jpg



Reference: 20260528_134245.jpg
